

365232-760

Application Instructions

For: H2, H3, 9731

SURFACE PREPARATION:

- 1.) Use a non-residual cleaner (i.e. Isopropyl Alcohol)
Thoroughly clean the area where the seal is to be applied and wipe dry. Dry thoroughly!
- 2.) Apply a protective coating to all raw metal openings before application of adhesive.

APPLICATION:

- 1.) Take seal in hand and begin peeling the release paper about 2 feet at a time. Firmly press the adhesive side of the seal down to insure good adhesion.

DO NOT STRETCH THE SEAL!

- 2.) Finish the seal application by continuing about ¼" beyond the point of and cut off excess. Pick up starting point and butt the two ends together. Firmly press ends together.

IMPORTANT NOTICE:

Products sold with pressure sensitive adhesives are subject to the following requirements.

- 1.) Handling, application area, and surface must be clean of Any contaminants such as dust, wax, dirt, or grease.
- 2.) Do not apply to any surface when temperatures are Below 60 degrees F. and/or above 85 degrees F. as the adhesive may fail to preform properly.
- 3.) Apply without stretching.

- 4.) **STORAGE:** The material should be stored in a cool dry area, circa 70+/-6 degrees F., to ensure the uniformity and Performance of the product. We will not be responsible for the performance of adhesives that have not been stored properly And/or been stored for longer than six (6) months.

Buyers are advised to test all materials prior to purchase to determine suitability and effectiveness for the particular application.